



T.			U_f	I_f	U_{a1}	U_{a2}	U_{a3}	U_g	\emptyset	
			V	A	V	V	V	V	„	mm
AR 40	Low	1	6,3	0,3	280	18000	11000	-30 ÷ -50	$16 \frac{1}{8}$	410
AR 40 M	Low	2	6,3	0,3					400	
KFO 30	Gnd	3	2	1	130	1000	4000	-120	$11 \frac{13}{16}$	300
35 Ac	Low	1	6,3	0,3	280	1800	11000	-30 ÷ -50	$12 \frac{1}{8}$	307
12 AP 4	amer	4	2,5	2,1	250	1200 ÷ 1800	7000	-20 ÷ -75	$10 \frac{3}{4}$	273
12 AP 4 A	amer	4	2,5	2,1						
1803 P 4	RCA	4	2,5	2,1						

